

Packing List For
CALTECH #2

Dwg/Part #	Part Description/Material	Qty
-----traveler E070316-----		
D071067	Spring Hatch, Optics Table	3
D071074	Flexure Post	3
D071105	Flexure Lower Plate	3
D071120	Actuator Magnet Mount	6
D071121	Actuator Coil Support	6
D071122	Actuator U-Bracket, Vert	6
D071129	Actuator Setup Bar	7
D071132	Actuator L-Bracket, Horiz	6
D071140	Locker Base	4
200047932	Sleeve, Housing	4
200047936	Base (D-1)	4
200047936	Cap (D-2)	8
D071180	GS13 Adapter Plate	6
D071250	Barrel Nut (Type 00)	189
D071250	Barrel Nut (Type 01)	626
D071250	Barrel Nut (Type 02)	130
D071255	Wiring Breadboard	10
D071009	Particle Fence, AL 6061	3
D071160	Sensor Target Mount, AL 6061	6
D071161	Sensor Head Base, AL 6061	6
D071162	Sensor Head Washer, AL 6061	6
D071163	Sensor Head Mount, AL 6061	6
D071164	Sensor Head Base Plate,AL6061	6
D071165	Sensor Target	8
D071166	Sensor Target Body, AL6061	6
D071170	Sensor Head Standoff, Horiz, AL 6061	3
D071175	Sensor Head Standoff, Vert, AL 6061	3
D071183	GS-13 Cable Restraint, AL6061	8