

Packing List For
CALTECH #1

Dwg/Part #	Part Description/Material	Qty
-----traveler E070316-----		
D071004	Support Post Gusset, Aux	3
D071005	Support Post Gusset, Main	3
D071007	Stiffener Plate, Type 00	1
D071007	Stiffener Plate, Type 01	4
D071008	Stiffener End Cap	2
D071052	Rib, Tan, GS-13 Mid	3
D071053	Rib, Tan, GS-13 Cen	3
D071054	Rib, Rad, GS-13 Mid	3
D071055	Rib, Rad, GS-13 Out1	3
D071056	Rib, Rad, GS-13 Out 2	3
D071057	Outer Wall, Horiz GS-13	3
D071058	Outer Wall, Flexure Access	3
D071059	Outer Wall, Small Panel	9
D071060	Outer Wall, Bracket 120 type00	6
D071060	Outer Wall, Bracket 120 type01	6
D071061	Outer Wall, Bracket 90	9
D071063	Keel Wall	6
D071065	Keel Base	1
D071068	Rib, Rad, Flexure Out 1	3
D071069	Rib, Rad, Flexure Out 2	3
D071070	Rib, Tan, Flexure Cen	3
D071071	Rib, Tan, Flexure Mid	3
D071072	Rib, Tan, Flexure Mid Cover	3
D071073	Rib Bracket, 60 Deg	6
D071075	Flexure Post Bracket, Tan	3
D071076	Flexure Post Bracket, Rad	3

-----traveler E070317-----

Accuglass	Cable (PN600202)	6
Accuglass	Cable (PN600200.1)	2